

Building Better Buildings

22nd March 2016

Cardiff



Innovate UK

ADEILADU
ARBENIGRWYDD
YNG NGHYMRU



CONSTRUCTING
EXCELLENCE
IN WALES



Ed Evans

Director

Constructing Excellence in Wales



BUILDING BETTER BUILDINGS BREAKFAST SEMINAR




22th. March, 2016

ROLE OF THE ZERO CARBON HUB

PURPOSE AND STRATEGIC OBJECTIVES

Facilitate the mainstream delivery of low and zero carbon homes working across borders

- Provide leadership and create confidence
- Reduce risk
- Disseminate information




CLIMATE CHANGE

The Road to Zero Carbon




CLIMATE CHANGE – EXPECTED INCREASE IN TEMPERATURE






KYOTO – WHO'S ON TARGET




POLICY: A 'EUROPEAN' CONTEXT



An interesting time for new buildings



Nearly zero-energy Buildings



EPBD Article 2, NZEB definition:

[..] ‘nearly zero-energy building’ means a building that has a very high energy performance [..]. The nearly zero or very low amount of energy required should be covered to a very significant extent by energy from renewable sources, including energy from renewable sources produced on-site or nearby.[..]

Article 9 Nearly zero-energy buildings – EPBD

1. Member States shall ensure that:
 - (a) By 31 December 2020, all new buildings are nearly zero-energy buildings; and
 - (b) After 31 December 2018, new buildings occupied and owned by public authorities are nearly zero-energy buildings.
 - (b) Set targets in order to stimulate the transformation of buildings that are refurbished into nearly zero-energy buildings

CARBON CULPRITS




CARBON CULPRITS IN UK BUILDINGS



Culprits: most CO2 from buildings stems from heating. Houses are particularly energy-inefficient

RISKS

- **Performance gap** – moving to solutions
- **Ventilation** – encouraging best practice
- **Overheating** – understanding the issues



THE PERFORMANCE GAP






Golf TD Clean Diesel
2009 World Car of the Year

NOT A CONCEPT CAR



WHAT ARE CONSUMERS EXPECTING?

This is why the performance gap matters



Core Work Groups

- WG0: Process
- WG1: Concept & Planning
- WG2a: Design
- WG2b: Tools
- WG3a: Materials & Procurement
- WG3b: Procurement
- WG4: Construction
- WG5a: Verification
- WG5b: Testing
- WG5c: CJDs




Closing the Performance Gap – the 2020 Ambition:

“From 2020, be able to demonstrate that at least 90% of all new homes meet or perform better than the designed energy / carbon performance”




Literature Review



- **State of the industry (*aggregated data*)**
 - NHBC, LABC, SAP software providers, professional institutions, house builders, manufacturers
- **Compliance processes**
 - As-built SAPs, ACD/ECD use, Air pressure tests, commissioning
- **Field trials**
 - TSB Building Performance Evaluation, EST Heat pump trials
- **Academic studies**
 - Stamford Brook, Elmtree Mews, Temple Avenue
- **“Secret” knowledge**
 - Manufacturers, Universities



Prioritisation of issues



- 15 Priority for Action

AND cross-cutting themes



KNOWLEDGE & SKILLS



RESPONSIBILITY



COMMUNICATION

Evidence Review Report



CONCEPT DESIGN & PLANNING



Limited understanding of impact of early design decisions on energy performance

DETAILED DESIGN



Inadequate understanding and knowledge within detailed design team

D2

Lack of integrated design between fabric, services & renewables



Issues around use of U-value and thermal bridging calculation procedures

EM7

Concern over competency of SAP assessors

PROCUREMENT



Inadequate consideration of skills and competency at labour procurement

CONSTRUCTION & COMMISSIONING

C5

Product substitution on site without consideration of energy performance

C15

Poor installation of fabric

C9

Poor installation or commissioning of services

C13

Lack of site team energy performance knowledge & skills

C6

Lack of adequate energy performance related QA on site

VERIFICATION & TESTING

T3

Concern over consistency of some test methodologies & interpretation of data

EM4

As-Built SAP not reflective of actual build

V2

Lack of robust energy performance related verification, reliance on third party information

V5

Lack of clarity over documentary evidence for Part L & Part F compliance

Inadequate Understanding & Knowledge within Design Team

Impact on:

- Buildability
- Compatibility of systems, materials and services
- Thermal detailing

Typical examples:

- Details into which insulation is impossible to fit
- No detail on support of screed at ground floor perimeters
- No consideration of thermal bridges for rooms over garages

Concern over Competency of SAP Assessors


Problems with:

- Accuracy of inputs
- Following conventions
- Validating assumptions
- Evidencing assessments




Massive impact where they are giving design advice

How is the u-value calculated?



Can't assume same thickness across entire roof



Lack of Site Team Energy Performance Related Knowledge and Skills and/or Care

Literature Review -


- *“The lack of proper training of the workforce.....resulted in significant construction faults, unplanned design solutions and wrong system commissioning”*

Oxford Brookes University, Understanding the Gap between As Designed and As Built Performance, 2013



Windows located in front of design positions

- Insufficient overlap with cavity closer
- All sites visited had the window in the wrong place



Product Substitution On Site

Literature Review -

- *“The most striking observation about the application of materials and components were the number of occasions on which materials intended for one location were used in another”*

Leeds Metropolitan University, Lessons from Stamford Brook, 2008





**Performance
Assessment R&D**

**Skills and Knowledge
Development**

**Construction Details
Scheme**

**Continued Evidence
Gathering**

INDUSTRY RECOMMENDATIONS



Signal Clear Direction

**Stimulate Industry
Investment**

**Strengthen
Compliance Regime**

**Support Skills &
Knowledge
Development**




GOVERNMENT RECOMMENDATIONS




How to address the Performance Gap?

- Provide a good practice guide in simple, clear format
- Use with on site toolbox talks, site manager training, builder's merchants, building control, designer awareness, specifications, warranty providers And students !




Performance gap - First step to solutions



Common themes on site Site Posters - Fabric and Services

Fabric

- 1 Groundworks
- 2 Beam and Block Floor
- 3 Door Threshold
- 4 Cavity Wall – partial fill
- 5 Cavity wall – full fill
- 6 Floor Joists
- 7 Separating wall
- 8 Lintels
- 9 Windows
- 10 Bay windows
- 11 Projecting windows
- 12 Eaves
- 13 Roof
- 14 Dryline
- 15 Ventilation
- 16 Heating / hotwater
- 17 Finals





Site posters

ZERO CARBON HUB BUILDERS' BOOK


CAVITY WALL



PROBLEM TO AVOID GAPS IN INSULATION



WHAT TO DO?



GOOD PRACTICE

1. Protect cavity and insulation from mortar droppings
2. Smooth mortar joints to allow insulation board tight against block
3. Install insulation tightly butted with no gaps
4. Cut insulation tight to cavity closers, lintels and cavity trays

Please print and use in your site office,
for further information www.zerocarbonhub.org





ZERO CARBON HUB BUILDERS' BOOK

CAVITY WALL




PROBLEM TO AVOID MISSING INSULATION



WHAT TO DO?

- Install rigid insulation behind steel beams, cavity trays, meter boxes and subfloor vents or any other elements bridging cavity
- Blown or injected insulation, ensure this reaches the whole wall with no gaps
- Adjust drill pattern for tight spots, cavity trays and inject below DPC



CUT INSULATION AROUND CAVITY TRAY

GOOD PRACTICE

Use preformed tray around complex junctions

Please print and use in your site office,
for further information www.zerocarbonhub.org



WINDOW INSTALLATION




9.0

PROBLEM TO AVOID WINDOWS INSTALLED FORWARD OF DESIGN POSITION




COLDSPOT



NO OVERLAP OF WINDOW AND CAVITY

WHAT TO DO?

- Close the cavity with tightly packed insulation (1)
- Insulation to window reveal (2)
- Window fitter to provide non standard large cill (3)
- Overlap frame with cavity as much as possible - minimum 30mm
- Check trickle vent sizes as design
- Less than 10mm tolerance around window frame and structural opening



GOOD PRACTICE

A large overlap with cavity will improve thermal performance
For improved airtightness, use air barrier tapes between the window/door and structure

EAVES




12.0

PROBLEM TO AVOID NO INSULATION AT EAVES



SQUASHED INSULATION




WHAT TO DO?

- Install rigid insulation to top of the wall plate (1)
- Truss design to accommodate space for insulation at eaves (2)
- Lay mineral wool insulation into eaves (3)
- Cut insulation around eaves lintels


OPTION 1



OPTION 2



© CREST NICHOLSON



GOOD PRACTICE

Install insulation before eaves are inaccessible



GROUND WORKER



BRICKLAYER



CARPENTER



PLUMBER



ELECTRICIAN



PLASTERER



WINDOW FITTER




ROOFER



DECORATOR

Zero Carbon Hub Guides



The 7 Brothers; Guiding SME's

1. Builders' Book - Masonry
2. SAP Untangled
3. Thermal Bridging Guide
4. Design Guide
5. Cost Efficiency Handbook
6. Services Simplified
7. Builders' Book - Timber Frames

VENTILATION





Ventilation – delivery improvements



Ventilation Field Study

- Focus on MEV and MVHR
- Site walkthrough investigations
- Interviews with key people:
 - Installers
 - Site management
 - Designers
 - Manufacturers
 - Residents



OVERHEATING



OVERHEATING – a few numbers

- 20% No of homes in England & Wales are already O/Htg
- 1 in 3 2,000 excess deaths in UK every third year by 2040
- 9° C Biggest recorded Urban Heat Island Effect (London v rural)
- £100K Cost to one builder to rectify an O/Htg apartment block
- 7,000 Estimate of 2050 annual heat related deaths
- 100 Estimated hospital admissions for every heat related death




Helping the Consumer

Are the running costs as presented by the EPC of any use?

Are homes today comfortable?

Are we creating 'stuffy' homes?


Energy Performance Certificate

1 Insulation Avenue, London W4 1UV

Dwelling type: End-terrace house	Reference number: 8009-8677-9829-3096-4423
Date of assessment: 13 April 2012	Type of assessment: RdSAP, existing dwelling
Date of certificate: 10 April 2012	Total floor area: 88 m ²

Use this document to:

- Compare current ratings of properties to see which properties are more energy efficient
- Find out how you can save energy and money by installing improvement measures

Estimated energy costs of dwelling for 3 years:	£3,243
Over 3 years you could save	£1,521

Estimated energy costs of this home

	Current costs	Potential costs	Potential future savings
Lighting	£237 over 3 years	£141 over 3 years	<div style="background-color: #2e7d32; color: white; padding: 10px; width: 50px; margin: 0 auto;"> You could save £1,521 over 3 years </div>
Heating	£2,712 over 3 years	£1,395 over 3 years	
Hot Water	£294 over 3 years	£186 over 3 years	
Totals	£3,243	£1,722	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances like TVs, computers and cookers, and any electricity generated by microgeneration.

Energy Efficiency Rating

<p style="font-size: 0.8em;">Very energy efficient - lower running costs</p> <table border="0" style="width: 100%;"> <tr><td style="background-color: #2e7d32; color: white; padding: 2px;">(92 plus) A</td></tr> <tr><td style="background-color: #4caf50; color: white; padding: 2px;">(81-91) B</td></tr> <tr><td style="background-color: #8bc34a; color: white; padding: 2px;">(69-80) C</td></tr> <tr><td style="background-color: #ffc107; color: white; padding: 2px;">(55-68) D</td></tr> <tr><td style="background-color: #ffc107; color: white; padding: 2px;">(39-54) E</td></tr> <tr><td style="background-color: #ff5722; color: white; padding: 2px;">(21-38) F</td></tr> <tr><td style="background-color: #ff0000; color: white; padding: 2px;">(1-20) G</td></tr> </table> <p style="font-size: 0.8em;">Not energy efficient - higher running costs</p>	(92 plus) A	(81-91) B	(69-80) C	(55-68) D	(39-54) E	(21-38) F	(1-20) G	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr style="background-color: #0056b3; color: white;"> <th>Current</th> <th>Potential</th> </tr> </thead> <tbody> <tr> <td style="width: 50px; height: 100px;"></td> <td style="width: 50px; height: 100px; text-align: center; vertical-align: middle; font-size: 1.5em;">83</td> </tr> <tr> <td style="width: 50px; height: 100px; text-align: center; vertical-align: middle; font-size: 1.5em;">49</td> <td style="width: 50px; height: 100px;"></td> </tr> </tbody> </table>	Current	Potential		83	49	
(92 plus) A														
(81-91) B														
(69-80) C														
(55-68) D														
(39-54) E														
(21-38) F														
(1-20) G														
Current	Potential													
	83													
49														

The graph shows the current energy efficiency of your home.

The higher the rating the lower your fuel bills are likely to be.

The potential rating shows the effect of undertaking the recommendations on page 4.

The average energy efficiency rating for a dwelling in England and Wales is band D (rating 60).

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Cavity wall insulation	£500 - £1,500	£69	✔
2 Internal or external wall insulation	£4,000 - £14,000	£576	✔
3 Floor insulation	£800 - £1,200	£129	✔

See page 4 for a full list of recommendations for this property.

To find out more about the recommended measures and other actions you could take today to save money, visit www.direct.gov.uk/savingenergy or call 0300 123 1234 (standard national rate). When the Green Deal launches, it may allow you to make your home warmer and cheaper to run at no up-front cost.



<http://www.zerocarbonhub.org/recent-publications>

Stay in touch:
www.zerocarbonhub.org
Rob.pannell@zerocarbonhub.org

Thank you



Building Performance Evaluation: In-use Post Occupancy Evaluation – a Welsh Case Study

Aberfawr Terrace, Abertridwr, Wales

Building Better Buildings - Cardiff

22nd March 2016

Dr John Littlewood*^

**Director* – Sustainable Construction Monitoring & Research Ltd

^Head of the EBERE group, Cardiff Metropolitan University

scmr2410@gmail.com and jlittlewood@cardiffmet.ac.uk

Project partners

United Welsh Housing Association (BPE grant winner), Caerphilly, Wales


InnovateUK

Sustainable Construction Monitoring & Research Ltd, Dinas Powys (2012-date)

Cardiff Metropolitan University (2011-2012, 2015-date), Cardiff, Wales

Thanks to: Richard Mann, Ivan Smallwood, Mat Colmer, Alex Moody

Introduction – Aberfawr Twerrace, Abertridwr



Altitude is 155 metres above sea level, side of a river valley.

Orientation is north/south (flats) and west/east (houses).

Designed and constructed as a package deal with a Welsh contractor.

Occupied from December 2010: nine single-storey flats, four two-storey houses and one fly-over maisonette.

BPE study: two flats (single occupancy), one two-storey house, two bedrooms (2 adults/1 child) and one two-storey house, three bedrooms (multiple occupancy).

Introduction – Aberfawr Terrace: Dwellings

- All houses CfSH level 3+ and flats CfSH level: 4, latterly DECC grant during construction in 2010.
- Flat construction - 0.2, 0.1 and 0.25 W/m²K U values for exterior walls, roof and ground floor, timber frame, sheeps wool insulation, cedar clad, triple glazing, 1 kW PV;
- House Construction: 0.18, 0.1 and 0.2 W/m²K U values for exterior walls, roof and ground floor; brick/block cavity construction, double glazing, no PV.
- Heating/Ventilation: electric only: NIBE EASHPs + underfloor heating



Littewood et al, (2014, 2016)



Key questions: Design Intent Vs Actual Building Performance.

1. How does timber frame versus brick/block construction effect dwelling internal comfort conditions, space heating energy use and carbon emissions?
2. Do NIBE EASHPs lead to high energy usage and associated costs/carbon emissions for space/water heating, and how to occupants engage with such systems and their controls.
3. How can the handover/tenant education be developed and used on other schemes and can any lessons be learnt from the contractor's direct supply approach?
4. How do air tightness values that exceed the maximum optimum of $3 \text{ m}^3/\text{h.m}^2$, at $4.8 \text{ m}^3/\text{h.m}^2$ (houses) affect the use of the EASHPs.
5. UW wishes to understand whether it needs to fundamentally overhaul its design, procurement, commissioning and hand-over strategies; by stipulating more exacting design, construction, commissioning and operational standards.

Littewood et al, (2014, 2016)

Systems Review: Underfloor Heating Controls & Heat Pump Controls

House



Flat



House



Littewood et al, (2014, 2016)

Systems Review: Thermostats

Flat
Room
Thermostat



House
Room
thermostat



Both dwellings are similar as far as the local room controls are concerned. The thermostats in House . were set to maximum (30°C),

Flat
Hall
(main)
Thermostat



House
Hall
(main)
Thermostat



Littewood et al, (2016)


Occupant interaction with extract ventilation & filters



Littewood et al,
(2014, 2016)

Occupant interaction with supply ventilation

Air make-up (to replace the air extracted by the NIBE system) is via wall transfer grilles in each property. These are located in each of the non-wet rooms, i.e. living rooms and bedrooms. This type of air inlet and the installed capacity is appropriate for this type of ventilation system. As often found, however, is the tendency for occupants to close these (Figure 2.6), either due to perceived heat loss, or discomfort from draughts, or both. Two out of the three air inlets in House 4 were found to be closed, and two out of two air inlets in Flat 6A were found to be closed. This finding is symptomatic of poor user guidance and understanding and it is recommended that guidance is made available as detailed earlier in this report.



Littewood et al,
(2014, 2016)

Some key Findings Monitoring vs SAP – Heating: Flat & House

Energy	2010-SAP	2014-SAP	Monitored data	% monitored value of SAP value	
Total Heating Energy Usage (kWh/yr)*	2051.63	2307.25	1628.50	79.37	70.58
S/Heating Energy Outputs (kWh/yr)	1387.70	3149.83	1244.00#	89.64	60.51
H/W Heating Energy Outputs (kWh/yr)	2111.63	1533.46	342.00#	16.20	22.30


Energy	2010-SAP	2014-SAP	Monitored data	% monitored value of SAP value	
Total Heating Energy Usage (kWh/yr)*	2858.93	3376.83	4009.80	140.26	118.74
S/Heating Energy Outputs (kWh/yr)	2417.51	6463.01	2046.00#	84.63	31.65
H/W Heating Energy Outputs (kWh/yr)	2608.35	1855.38	2558.00#	98.07	137.87

*heating values includes energy usages for heat pump, immersion and, pumps, fans and controls.

#monitored heating, space and hot water, energy outputs (NOT USAGE).


(Littlewood & Smallwood, 2015)

Some key Findings Monitoring – Energy Usages all dwellings



Occupancy patterns are linked to higher energy usage as are greater exposed facades

Some key Findings Monitoring – EASHP COP: House




The Derived CoP values are unusual. Notable, the maximum Derived CoPs occur in the SAP non-heating period; July to September, before the first heating period begins.

NIBE SYSTEM	NIBE-Published CoP	Derived CoP Maximum (Difference)	Derived CoP Minimum (Difference)
Fighter 360P	3.40	2.09 (-1.31)	0.655 (-2.75)

Environmental Conditions Review: Monitored Data


Internal Monitored Daily Non-living-space (Bedroom-1 [East-facing]) Temperatures for BB-H1



Underheating/Overheating - cause may not be the M&E, occupants could be the fabric

Some key Findings Monitoring – Environmental Conditions House

Internal Monitored Daily Living-space (Lounge) Temperatures for BB-H1



Underheating/Overheating - cause may not be the M&E, occupants could be the fabric

Some key Findings from the System Inspection & occupant Interaction

- The EASHP heating-curve 'set-point' for both dwellings was set to the manufacture's settings for radiators not under-floor heat output sources.
- In the house, the 'selected' heating-curve and heat-supply output was set for climates akin to Sweden with external temperatures of -20C and the Swedish language.
- Ceiling terminals for extracting air from some rooms: inspected as altered and also dust, grease and particulate matter was found to be blocking the ducting, both.
- Monitored data indicates that overall the flat never sustains the SAP-Adjusted internal comfort temperature suggesting little heat is recovered through the ceiling ducts & underfloor heating was faulty.
- Both house and flat: overall air flow, (m^3/h^{-1}), is 35% higher & 26% lower in house/flat than the manufacture's recommendations: affecting indoor air quality, heating demands and heat recovery.
- Both house and flat: occupants 'fail' to understand the 'nuances of the installed EASHPs/under-floor heating, operated as 'turn-on/off' & timed – even after repeated instructions during handover, and the BPE project. Filter cleaning problem.

Heating, Thermostats, Occupants or Fabric causing inadequate performance

	As Built Air Permeability - 2010	Air Permeability 2014 Test Result	Difference
Flat	2.9 m ³ / (h.m ²)@50Pa	3.72 m ³ / (h.m ²)@50Pa	+0.82 m ³ / (h.m ²)@50Pa
House	4.8 m ³ / (h.m ²)@50Pa	8.8 m ³ / (h.m ²)@50Pa	+4.00 m ³ / (h.m ²)@50Pa



Littewood & Smallwood (2015)

Some Key conclusions from Abertridwr

The incorrect testing/commissioning of the installed heating and ventilation systems means that, regardless of other external factors, the installed EASHP-systems cannot operate to the manufacture's efficiencies.

So difficult to draw conclusions of the effectiveness of the installed technologies in reducing energy consumption, associated emissions and operating costs.

This BPE study highlights the existence of a 'knowledge gap' within the end-users, occupants have developed behaviour strategies in the provision of their internal comfort levels and environmental conditions using the installed heating and ventilation.

Certain actions have a significant detrimental effect which further exasperate the effectiveness of the installed systems and are also reflective of the barrier between users and new technologies in that there 'appears' to be evidence that older technologies; central heating and extractor fans for example, provide a greater feeling of control of the end-user internal environments.

Key Messages

It appears that the Design and Build and complete package deals, where the contractor retains the majority of the control until handover, may not be suitable for innovative developments using non-standard design, construction and systems.

The local authority building control must be active in checking construction compliance on site throughout the process until handover, to ensure responsible and true certification. In addition, the NHBC should also take an active part in this process to ensure that construction and installation meets design intents.

The 'Performance Gap' does not stop post-construction; the processes of an informed handover to future occupants and a robust maintenance management programme is need to ensure that the properties are used and maintained as to the original design intents if energy-efficiency and low-costs benefits are to be continually realized.

Building performance in the life-time of a property is ultimately dependent upon the occupier's ability and willingness to use the building and systems to the original design intents and not rely on others to manage this on their behalf.

The BPE study further highlights the current serious questions within sustainable construction as to applicability/enforceability of the current raft of regulations, policies and standards so that design intents are translated into actual long-term usable benefits.

Lessons embedded at United Welsh

During the BPE project, a dedicated staff member was employed within the development team for managing handover of projects to tenants;

Post BPE study, a new development inspector (clerk of works) was employed to specifically focus upon construction performance during the build stage, with both architectural design and construction experience

SCMR Ltd retained post BPE to offer guidance on compliance testing: air test observations, conducting independent air tests, thermography tests, and whole dwelling smoke tests.

REFERENCES

LITTLEWOOD, J. R. DAVIES, G, J. SMALLWOOD, I. 2014. Energy and Environmental Performance of the Abertridwr Community – First Winter Season. *Energy Procedia*, Volume 62, December, Pages 532–542.

LITTLEWOOD, J. R. SMALLWOOD, I. 2015. Testing Building Fabric Performance and the Impacts Upon Occupant Safety, Energy Use and Carbon Inefficiencies in Dwellings. *Energy Procedia*, Volume 83, December, Pages 454-463.

LITTLEWOOD, J. R. SMALLWOOD, I. 2016. Annual Energy and Environmental Performance of the Abertridwr Community. *Energy Procedia*, Volume Tbc, December, Pages Tbc.



THANK YOU FOR YOUR ATTENTION

ANY QUESTIONS

The Main Place Coleford Community Centre



Building Performance Evaluation

Piers Sadler


**PIERS
SADLER
CONSULTING**


- Passivhaus Design & Consultancy
- Building Energy & Science
- Building Performance Including
 - Refurbishment/New Build
 - Domestic/Non-Domestic

www.piers-sadler.co.uk

**CERTIFIED
PASSIVE HOUSE
DESIGNER**

**PIERS
SADLER
CONSULTING**





CERTIFIED
PASSIVE HOUSE
DESIGNER

PIERS
SADLER
CONSULTING

Building Performance Evaluation

The Main Place

- Client: Innovate UK
- Lead Consultant: Quattro Design Architects
- Sub-Consultant: Piers Sadler Consulting
- Sponsorship: Gloucestershire County Council
- Support (Dissemination): Constructing Excellence
- Duration: July 2012-October 2014



Project Background

- **Kier Construction - Design and Build Contract**
- **Occupied from February 2010**
- **Four user groups – CAP, Library, Youth and Learning and Disability Services, shared hall and catering**




Handover

- Training (DVD)
- Documentation (BREEAM points)
- Defects:
 - Door security
 - Heating pipes (plant room)
 - Mikrofill – pressure maintenance system
 - Water boilers
 - Meters
 - Cracks



Systems

- Gas Boilers
- UFH in Library & Hall – radiators everywhere else
- Zone 1 DHW from boilers + solar thermal
- Distributed electric water heating in rest of building
- Air Handling Unit with heat recovery – hall
- Overhead door heater
- Kitchen
- Air conditioning unit – IT suite and IT server
- Lighting – PIR sensors automated



Thermographic Survey



Metering and BMS


- 6 zones all sub-metered for electricity and heat

BUT

- Electrical sub-meters not properly commissioned
- Gas meters not properly calibrated
- Heat sub-meters not capable of communicating with BMS
- BMS not correctly reading electrical meter pulses




Electricity Metering - Reconciliation



77%
electricity
usage
accounted
for:
Plant room,
pumps, fans
and controls
not sub-
metered


Gas/Heat Metering - Reconciliation



92% of gas energy accounted for


Annual Energy Review

Electricity




Annual Energy Review

Gas/Heat



Annual Energy Review

Gas/Heat





~£1500/yr to heat the hall

~£500/yr youth heating

Issues Arising and Interventions

Zone 6 Heating



Issues Arising and Interventions

Air Handling Unit



Supply

Extract

Issues Arising and Interventions

Air handling unit heater & frost protection




Options:

Drain system, remove heater, re-route circuit (£2600)

Change frost protection settings (within project cost)

Issues Arising and Interventions

Changes to frost protection




Extrapolated to the year 9000kWh or ~£250

Issues Arising and Interventions

Zone 2 - Library Heating

- UFH & radiators on same circuit
- Radiators running at $\sim 50^{\circ}\text{C}$




Issues Arising and Interventions

Zone 2 electric heaters




- ~£189/yr additional cost of electricity for fans
- £3200 to install thermostat on UFH manifold and reprogramme BMS to provide 70°C water to radiators (not done)

Issues Arising and Interventions



Issues Arising and Interventions

Zone 1 Domestic hot water (DHW) & solar thermal



Note also numerous uninsulated valves and gauges

Issues Arising and Interventions

Distributed electric water heaters

- Zone 3 Hot Water – needs to be left on 24/7 for cleaners
- Some water heaters inaccessible so can't be controlled



Issues Arising and Interventions

Lighting

- Youth and CAP offices
- Hall cupboards, gallery, youth activity area – PIR adjustments (£8/yr)
- Youth ‘lounge’ (resolved)



Interventions and Improvements Behaviour

- Operations and behaviour:
 - Water heaters turned off at night
 - TRVs turned down in Zone 5
 - Kettle used in favour of water boiler Zone 1
 - IT suite air con turned off in winter
- Building User Guide and Labelling

Building User Guide



Simple ON/Off Controls and Temperature Set Point

Use only on hot days – a 20 or 21°C set point should be sufficient



Programmable controls – basic features only required

IT Server room – use in Cooling Mode only with continuous operation and a temperature set point of 25°C

Labelling



Labelling...

to encourage energy saving behaviour



Labelling...

to explain controls




Other issues


- Computers 24/7/365
- BMS Zone pumps running in summer
- Temperature set points eg circulation area set to 21°C
- BMS access – ensuring users can change their settings in accordance with usage




Projected Improvements Thermal



Projected Improvements Electrical



Projected Improvements Emissions



Conclusions

- Building handover lacks a user focus
- Buildings metering not fit for purpose
- Influence of BREEAM credits –meters, documentation, solar thermal – present but not useful
- Effort spent at commissioning and handover has potential payback throughout the life of the building
- No and low cost opportunities to save energy and cost across the building stock



Thank you
Questions/Discussion

Q&A

